
Isabella County Time of Transfer Environmental Health Impact

433

Onsite sewage treatment systems and drinking water wells evaluated.




71%

of drinking water wells that were designed, maintained, and providing safe water in adequate quantity.



72

Homes with sewage surfacing, backing up, damaged septic tank, laundry or kitchen waste discharging on the ground surface.



Sewage surfacing at end of drainfield

13

homes without a drainfield found, (suspected but unconfirmed illicit discharges) representing approximately 1,423,500 to 2,135,250 gallons of wastewater a year no longer (potentially) being discharged to our waterways or groundwater.

15

Sewage disposal systems located less than 50 feet to a drinking water well or surface water. A minimum of 50 feet is the established standard to ensure bacteria and viruses are killed before they can contaminate our water.



Cracked septic tank

75% of onsite sewage treatment systems functioning properly.



Central Michigan District Health Department

Promoting Healthy Families, Healthy Communities

www.cmdhd.org